

SPRING CENTERED TAP GUIDE



- Points hardened upto 50-55 HRC.
- For use with drill chucks to stroke the hardened point for accurate hand tapped threads.

Tap Guide in Use

For execution, the center's body should be gripped in a drill chuck or collet, while the hardened point is inserted into the middle of the tapping handle. The stroke of the center will follow the tap, assuring straight and accurate hand tapped threads. One universal size for all tapping applications

Cat. No.	SHANK DIA.
GSG-7739	1/2"
GSG-7741	12mm



www.garvintools.com