


## DRILL CHUCK ARBOR



- Drill chuck arbors are double ended steel shafts.
- One end is machined to fit a machine spindle and the other fits into the back of a drill chuck.



CAT.NO.	MORSE TAPER SHANK	JACOB TAPER SHANK
<b>A</b>		
GDA-7477	1	1
GDA-7478	1	2
GDA-7479	1	3
GDA-7480	1	4
GDA-7481	1	5
GDA-7482	1	6
GDA-7483	1	33
GDA-7484	2	0
GDA-7485	2	1
GDA-7486	2	2
GDA-7487	2	3
GDA-7488	2	4
GDA-7489	2	5
GDA-7490	2	6
GDA-7491	2	33
GDA-7492	3	1
GDA-7493	3	2
GDA-7494	3	3
GDA-7495	3	4
GDA-7496	3	5
GDA-7497	3	6
GDA-7498	3	33
GDA-7499	4	2
GDA-7500	4	3
GDA-7501	4	4
GDA-7502	4	5
GDA-7503	4	6
GDA-7504	4	33
GDA-7505	5	2
GDA-7506	5	3
GDA-7507	5	4
GDA-7508	5	5
GDA-7509	5	6
GDA-7510	5	33
<b>B</b>		
	TAPER SHANK ACC DIN -238	
CAT.NO	DRILL CHUCK TAPER	TAPER SHANK MORSE TAPER
GDA-7511	B 10	1
GDA-7512	B 12	1
GDA-7513	B 12	2
GDA-7514	B 12	3
GDA-7515	B 16	1
GDA-7516	B 16	2
GDA-7517	B 16	3
GDA-7518	B 16	4
GDA-7519	B 18	1
GDA-7520	B 18	2
GDA-7521	B 18	3
GDA-7522	B 18	4
GDA-7523	B 22	2
GDA-7524	B 22	3
GDA-7525	B 22	4